## SERVICE BULLETIN



No. : 0IVL20050018 Date : 2005-06-16

Model Buyer		Factory Factory Model Suffix Model No. Factory Factory Model Suffix Model No. EKHQ KU-17LZ23 AAPLKZ KU-17WDVD											
		Buyer N	Name	Buyer Cod US000001		er Name Al		er Code 00002	Buyer Name ZENITH	Buyer C			
EFFECTIVE DATE			2005-06-15			E	EFFECTIVE FROM(SERIAL NO.) 2005-06-16						5
Subject			KU-17LZ21 Low DVD audio level										
No.	Loc No.		Before Change					After Change			Note	K-Code	Remark
		_								0 10 0			

Part No

DESC./SPEC.

## Reason Of Change

Part No

Some customers reported the DVD volume level was low compared to that of RF. So the volume level in DVD mode was increased and made same as of RF mode. The micom version has changed for this reason (V3.13 -> V3.14).

KU-17LZ21\_micomChange.pdf

## \*\* FILE THIS SERVICE BULLETIN WITH YOUR SERVICE MANUAL

DESC./SPEC.

	NOTE(**) : IN	KEY-WORD CODE		
	Parts Set			
А	Original Early	Original or new parts may be used in early or late production sets.	1. To improve performance	
	New Late	Use original parts until exhausted, then stock new parts.	2. To improve productivity	
В	OriginalEarly	Original parts may be used in early production sets only.	3. To improve reliability	
	New Late	New parts may be used in early or late production sets. Use original parts where possible, then stock new parts.	4. Change of material or dimension	
	Original Early	New parts only may be used in early or late production sets.	5. Addition	
С	New Late	Stock new parts.	6. Deletion	
D	OriginalEarly	Original parts only may be used in early production sets.	7. Correction	
	New Late	New parts may be used in late production sets only.  Stock original and new parts.		

CHIEF ENGINEER , approved Factory.